




lathe stop button		
stop button.dch	Required power on breadboard	
	is about 25 mA.	
Robert R. Fenichel	2015-07-25	electronics (sheet 1/2)

to photointerruptor

J101

This pinheader
connected to dangling
RJ45 male, and thence
through female-female
to photointerruptor.

J102



lathe stop button	
stop button.dch	"not touched" means photointerruptor not interrupted
Robert R. Fenichel 2015-07-25	switches (sheet 2/2)